

PARISH DRIVE-ROUND: 27th February 2018: EARDISLEY

Follow-Up/Status Key: **Green: Closed/Complete; Amber: In Process (action known to be taken);** None: action requested, but status unknown/pending confirmation

Whitney on Wye

Issue	Description	Inspected/Assessed?	Agreed Action	Follow-Up/Status
01.	Footpath EE12: review state of the brook and vegetation along the banks along the first part of the path	Y	Following on from the ditch clearance that has recently been done in the Glebe field, water appeared to be flowing freely in the brook. It was agreed vegetation on the banks could do with being sprayed/cut back, but this was not urgent due to the season. It was noted a bridge walkway had been installed on public land across the brook to a property in Eastfields.	Closed (for the time being); the Highways Working Group would need to request the Lengthsman to undertake clearance when appropriate.
02.	Church lane: look at the reported issue with parking on the bend and possible solution options, including adding another bell bollard	Y	Various options were considered & discussed with Lara/the Lengthsman. The addition of a single bell bollard with a possible contribution from the local business owner	The PC approved funding of a bell bollard, with the business owner. However, this is currently on hold,

PARISH DRIVE-ROUND: 27th February 2018: EARDISLEY

Issue	Description	Inspected/ Assessed?	Agreed Action	Follow-Up/Status
			was suggested. BBLP can source the bollards and Lengthsman can install as this is a specialist installation	pending wider discussions about parking in Eardisley.
03.	Church Road: dip in the surface of the new pedestrian crossing by the school is causing water to pool on the surface in heavy rain causing a hazard.	Y	This was supposed to have been revisited when the road through Eardisley was resurfaced. However, no action was taken. Lara to investigate.	In Process (BBLP)
03a.	Church Road: manhole covers on the recently resurfaced stretch of road are sunken & the surrounding surface is cracked in some places	Y	Lara took photographs & will ask for the issue to be investigated.	In Process (BBLP)
03b	Church Road: in heavy rain, surface water from the recently resurfaced road is causing flooding by the shop and the properties opposite, including stretches with dropped kerbs.	Y	Lara took photographs & the issue was discussed with the shop owner. Lara will ask for the issue to be investigated.	In Process (BBLP)
03c	Church Road: uneven/broken pavement edge close to the shop frontage was recently the cause of an accident involving an elderly person falling. The emergency repair	Y	Lara took a photograph and will report the issue.	In Process (BBLP)

PARISH DRIVE-ROUND: 27th February 2018: EARDISLEY

Issue	Description	Inspected/ Assessed?	Agreed Action	Follow-Up/Status
	was of poor quality, loose and uneven.			
04	Ditch/drainage issues reported alongside Woods Eaves Farm, Woodseaves Road	Y	This would be work for the Lengthsman. It was not deemed to be urgent currently but would need to be reviewed by the Highways WG.	Closed (for the moment.)
05	Review condition of ditch alongside the Hurstway on the Woodseaves Road	Y	The overhanging hedge had been cut since the previous inspection and no standing water was present in the ditch. However, running water was noted from the property out onto the road. Currently this was draining away but could be a cause for concern in periods of heavy rainfall.	Closed
06	A tree adjacent to an old bridge on the Woodseaves Road is pushing out the stonework towards the road and causing the bridge wall to lean	Y	Lara agreed this was an issue and raised a Works Order for repair works.	In Process (BBLP)
07.	Lower Welson / Bower Lane / The Dairy: Potholes, blocked drains &	Y	Everyone agreed this was a problem as water was pooling on the road by several	To be further considered by the HWG

PARISH DRIVE-ROUND: 27th February 2018: EARDISLEY

Issue	Description	Inspected/ Assessed?	Agreed Action	Follow-Up/Status
	ditches, flooding, road surface breaking up.		junctions, which would cause a hazard when temperatures dropped to freezing point. Lara will report it, but as the roads are minor roads this would not attract high priority. The Lengthsman has the resources to do remedial works, but it would be a major (expensive) task.	
08.	The Derry: Stream bank opposite the Derry has collapsed up to the edge of the tarmac. This was reported and reflection posts were erected, but no sign of repair to the road edge itself, which is deteriorating.	Y	Lara confirmed the Works Order raised included putting in additional support for the bank. This would be chased up.	In Process (BBLP)
09.	Queest Moor to Cokes Yeld: road surface hazardous to cyclists and vehicles, such as school buses.	Y	This area was deemed to be outside the parish	Closed
10.	Grips on A4111 towards Eardisley (just past the Crowe Turn and the A4112 junction) need digging out – blocked and cause a flood across the road surface.	Y	Lara advised this issue had already been reported and would be done in due course.	In Process (BBLP)

PARISH DRIVE-ROUND: 27th February 2018: EARDISLEY

Issue	Description	Inspected/ Assessed?	Agreed Action	Follow-Up/Status
11.	Broken kerb stones on junction of A438 with the Leominster Road need repairing/replacing	Y	Lara advised this issue had already been reported and would be done in due course.	Complete (August 2018)